

PLEASE SEE IMAGES BELOW FOR REMOVING-REPLACING LIGHT BULB ON THE C-1200M MICROSCOPE.



TWIST
COUNTER-CLOCKWISE
TO LOOSEN RETINING CAP



AND REPLACE BULB